NTN: Sample Decanting

(refer to SOP for complete instructions: http://nadp.slh.wisc.edu/lib/manualsSOPs.aspx)



Weigh bucket, lid, and sample. Complete block 6 of FORF.

Remove lid. Inspect sample for debris. Complete block 5 of FORF.

Decant sample into 1-L bottle from new, clean supplies. Avoid decanting debris. Dispose of excess sample.



Place matching bar code labels on FORF and bottle bag (or dry week envelope).



Complete the FORF.
If site has an electronic raingage, and data has been uploaded to NADP, block 7 can be completed using the tool at: http://nadp.slh.wisc.edu/precip/

Place FORF and bagged 1-L bottle in shipping box (or FORF in a dry sample envelope) and ship to:

Central Analytical Laboratory
2601 Agriculture Drive
Madison, Wisconsin 53718

Revised: 22 June 2018