




## NTN Thies Sensor Replacement, N-CON Collector

### Items needed:


- replacement Thies sensor
- Field Observer Report Form (FORF) for current week's sample

### Instructions:


1. Disconnect the sensor from the collector by unscrewing the connector.



2. Loosen the screws on either side of the mounting clamp to remove the sensor. Support the sensor so it does not fall when the clamp is loosened. Be careful not to drop the sensor.



3. Remove the old sensor and set it aside for return to the NADP Network Equipment Depot (NED).
4. Install the replacement sensor by repeating steps 1-2 in reverse order.
5. Record comment and date in Block 10 (**Remarks**) of the Field Observer Report Form (FORF).

<p><b>10. REMARKS</b> <small>For example: equipment malfunction, contamination, farming, burning, logging, leakage before weighing, etc.</small></p> <p><i>Sensor replaced on 12/11/2008.</i></p> 
---

6. Return the old sensor to the NED. Include a note describing the problem with the sensor.

NADP Network Equipment Depot  
465 Henry Mall  
Madison, Wisconsin 53706